Installing the Hotfix for Latitude ST

This hotfix resolves the following issues present with the Windows7 SP1 32-Bit on Latitude ST:

- Functionality issues on USB devices (Microsoft KB2528984)
- USB drivers are not updated after installing Windows 7 SP1 (Microsoft KB2529073)
- Stop error when restarting the system with certain Wi-Fi drivers installed (Microsoft KB2482122)
- Stop error when the system enters or resumes from the Soft Off power state (Microsoft KB2459268)

NOTE: This hotfix must be installed only if you re-image the Latitude ST and before installing any drivers.

Please perform the following steps to download the hotfix:

1. Go to **http://support.dell.com/support/downloads/**.
2. On the left navigation pane, click **Drivers Home**.
3. Enter the **Service Tag** or select the **Model**.
4. Under **System Utilities**, identify the latest **System Software** and click **Download**.

NOTE: For more information, refer to the Latitude ST **How-To Re-image Guide** available under **System Utilities**.

0KW4YJA00

2011 - 11